

Vehicle information

Mitsubishi 2012 PAJERO / MONTERO (V8#,V9#)

VIN:

Diagnostics time: 2021/05/30 15:22

Mileage:

Path: Manual selection > From 2006MY > EUR > PAJERO / MONTERO (V8#,V9#) > 2012 > 6G72 (3.0, S4, MPI) > LNHVL6Z > Diagnosis > Auto scan >

Status report

| System name | DTC counts | Status |
|------------------|------------|--------|
| MPI/GDI/Diesel | 2 | Fault |
| ABS/ASC/ASTC/WSS | 7 | Fault |
| SRS-Air Bag | 1 | Fault |
| Meter | 5 | Fault |
| IMMOBILIZER | 0 | Pass |
| SS4II/ES4 | 8 | Fault |
| AUTO CRUISE | 0 | Pass |
| Air Conditioner | 0 | Pass |
| ETACS | 4 | Fault |
| | | |

1. MPI/GDI/Diesel —— (2)

- 1.1. U1102 ASC/TCL/ABS timeout/Not equipped
Active DTC
- 1.2. U1073 Bus-off
Active DTC

2. ABS/ASC/ASTC/WSS —— (7)

- 2.1. 38 AT COMM.Line
- 2.2. 37 AT Fail
- 2.3. 36 ENG COMM.Line
- 2.4. 35 ENGINE Fail

- 2.5. 34 CAN COMM.
- 2.6. 67 ST SNSR Line
- 2.7. 74 COMB.SNS.Line

3. SRS-Air Bag —— (1)

- 3.1. U1073 Bus-off
Stored DTC

4. Meter —— (5)

- 4.1. U1109 ETACS CAN timeout/Not equipped
Stored DTC
- 4.2. U1112 SRS-ABG CAN timeout/Not equipped
Stored DTC
- 4.3. U1100 Engine CAN timeout
Stored DTC
- 4.4. U1101 T/M CAN timeout/Not equipped
Stored DTC
- 4.5. U1073 Bus-off
Stored DTC

5. SS4II/ES4 —— (8)

- 5.1. U1101 T/M CAN timeout/Not equipped
Stored DTC
- 5.2. U1100 Engine CAN timeout
Stored DTC
- 5.3. U1102 ASC/TCL/ABS timeout/Not equipped
Stored DTC
- 5.4. U1120 Engine (CAN message)
Stored DTC
- 5.5. C1453 SS4II Rear wheel speed sensor
Stored DTC
- 5.6. C1458 SS4II F/W engage SW
Stored DTC
- 5.7. U1121 T/M (CAN message)
Stored DTC
- 5.8. U1073 Bus-off
Stored DTC

6. ETACS — (4)

- 6.1. 01 SWS Communication Line/ETACS ECU
Active
- 6.2. 13 A/C CAN Timeout/Not equipped
Stored
- 6.3. 11 Engine CAN Timeout
Stored
- 6.4. 15 Display CAN Timeout/Not equipped
Active